| | | | | | 00010 |
|--|-------------|-------------|---|---|----------------------------|
| Appointment Day Date 9/25/24 Time Date Appointment Made NACHELE A. THOMAS REVUGABLE Customer TRUST PATED 6/0/2002 Address 40 TWIN OAKS City NATY State Zip BRIAN BUTLER Phone(H) Z41.4259 (W) | | | CHIMNE P.O. I Monterey | SEASON Y SWEE Box 341 y, CA 93942 77-3286 | PS |
| Number of fireplaces?Number of Chimneys? | | | Description | Cost | Work Ordered |
| CONDITION REPORT Unsatisf | facto | ory | | 24900 | 32940 |
| Type of Fireplace: Prefab Masonry \(\frac{\ | 1st Chimney | 2nd Chimney | Special Cap Top Sealing Damper Flashing Repair Crown Repair New Crown Waterproofing Fire Box Repair | | 135.00 |
| Chimney Cap | | | Heat Reflector/Shield | , | |
| Crown/Wash/Mortar Cap | | | Fireplace Screen | | |
| Bricks/Mortar Joints | | | New Liner Tuckpoint Flue | - | 29500 |
| Flue Liner | | - | Repair Smoke chamber | | 75 |
| | | <u> </u> | Smoke Guard Log Lighter | | 1 |
| Moisture Resistance | | | Ash Dump Door | | |
| Flashing | | | Clean Out Door | | |
| FIREPLACE | | | Dryer Vent Cleaning? Duct Cleaning? | | |
| Smoke Chamber | | | | | |
| Smoke Damage | | | | | - |
| Damper | | | Comments: | Sales Tax Total | |
| Firebox | | | SWEPT LOWER AREAS | Total Liggos | |
| Heat Reflector | - | | OF SYSTEM, PERFORMED | | |
| Loglighter | - | | EXISTINGSPARK ARRESTON | | |
| Ash Dump/Clean Out Door | | | SOFETY CAP FOR CODE, MO FLASHING NEEDS SEAL, N | | |
| PAID BY PAID BY Note: This sheet is a result of a visual inspection done at the of cleaning. It is intended as a convenience to our customer. | ne tin | ne | CLAY LINERS MISSING-AIRESTRACTORY COMENT. Work Authorized By | | LHIGHTEMP |

certification of fire worthiness or safety. Since conditions of use are beyond our control, we make no warranty of safety or function of

any appliance and none is to be implied.

Sweep Signature long Volue